

INTEL CORPORATION
3065 Bowers Avenue
Santa Clara, California 95051
(408) 987-8080
TWX - 910 338 0026 TELEX - 34-6372



September 1, 1987

Dear 80386 Customer:

We have identified 2 new errata items on the 80386 microprocessor. These errata are documented in the attached 80386 Stepping Information Sheet, dated September 1, 1987. We are sensitive to the effect any errata in the 386 may have on your business; we have thereby devised and verified several workarounds for these errata items so that you may have a choice of solution options. The workarounds are documented in the Information Sheet and in the attached hardware design.

If you have questions not covered by the attached documentation, please do not hesitate to contact your Intel Field Sales or Applications Engineer. Our field and headquarters applications staff are fully trained on these issues and are standing by to provide whatever help you need.

Sincerely,

A handwritten signature in black ink, appearing to read "Dana B. Krelle".

Dana B. Krelle
80386 Marketing Manager

Neali:
Call me if you
have any questions.
Justin Orion

80386-B1
STEPPING INFORMATION

REVISION: SEPTEMBER 1, 1987

This document contains specification changes, errata, and design notes. Specification changes listed are permanent; the 80386 data sheet will be modified to incorporate the changes. The errata items described herein will be corrected on future steppings of the 80386.

NOTES:

80386-B1 component identifier readable in DH after reset: 03H
80386-B1 revision identifier readable in DL after reset: 03H

At this time, B1 stepping parts are identified with one of the marks shown below:

11		11
11 A80386-16		11 A80386-20
11 S40344		11 S40362
11 (FPO number)		11 (FPO number)
11 (m) (c) 1 '85 '86		11 (m) (c) 1 '85 '86
ΣΣ		ΣΣ

REVISION HISTORY:

9/1/87 Specification change 10 updated
Specification change 11 added
Errata 20 and 21 added

Specification Changes

The specification changes listed in this section apply to the latest version of the 80386 datasheet, version -003 dated November 1986. This datasheet is part of the 1987 Microprocessor and Peripheral Handbook, order number 230843-004. Specification changes 3, 5, and 6 have already been incorporated into this datasheet; the remaining items will be included in future versions of the datasheet.

1. NT Bit and IOPL Bits in Real Mode

The NT bit and IOPL bits of the FLAGS register can be set in Real Mode of the 80386. The exact behavior of these bits in 80386 Real Mode was not previously documented. Note that in 80286 Real Mode, these bits can not be set (they always remain 0 in 80286 Real Mode).

2. Coprocessor Data Pointer Stored by FSAVE/FSTENV Instructions is Undefined after Non-memory Instructions

The contents of the operand address field resulting from a FSTENV or FSAVE are undefined if the preceding coprocessor arithmetic instruction did not have a memory operand. The exact contents of the operand address field in this case was specified previously. This now confirms that the operand address field is undefined in that case.

3. Bit String Insert and Extract Instructions Removed

Since the 80386 has unique and powerful 64-bit Double Shift instructions, and fast multi-bit shift and rotate instructions, the "Bit String Insert" and "Bit String Extract" instructions were removed. The insert/extract complex instructions did not provide an additional benefit that fully justified including them in 80386 silicon and all future compatible processors. A review concluded that the 80386 user obtains full performance in bit string manipulations using other powerful instructions such as 64-bit Double Shift, and other multi-bit shift/rotate instructions. These instructions support extremely fast manipulation of general unaligned bit strings of any length, by processing them in 32-bit chunks.

4. PC/AT Compatible Coprocessor Connection

Refer to the 80387 Stepping Information for a description of how to connect the 80387 to the 80386 in a PC/AT-compatible manner. A small amount of logic is necessary to use the PC/AT non-standard method of reporting coprocessor errors. When using the recommended 80386/80387 connection (80387 BUSY#, ERROR#, and PEREQ pins connected directly to the 80386), no special provisions are necessary.

5. Read Cycles Require Valid Data Bus Levels

The 80386 requires that all data bus pins be at a valid logic state (high or low) at the end of each read cycle, when READY# is asserted. The system MUST be designed to meet this requirement. Therefore, do NOT allow any data lines to be floating when the read cycle completes. NOTE: The I/O read cycles just mentioned in the previous item, item 4, are free from this requirement.

Implications: If the device being read is a 32-bit device, such as a 32-bit memory, the system should present 32-bits of data to the 80386 even if not all of the 80386 byte enables are asserted.

If the device being read is a 16-bit or an 8-bit device, however, pullup resistors can be used to guarantee valid logic levels on the upper data lines, which otherwise would be floating. Note that bus cycles to 16-bit and 8-bit devices typically include several wait states, but always

calculate the effects of R-C time constants to ensure the pullups will drive proper logic levels onto the bus within the time required.

6. I/O Permission Bitmap Must Reside Within TSS Offset 0FFFFh

The 80386 requires that the entire I/O permission bitmap (including the terminating byte of "0FFh"), which is part of an 80386 TSS, begin at an offset no larger than 0DFFFh. This guarantees the entire bitmap (up to 8 kilobytes + 1 terminator byte of 0FFh) will reside at TSS offsets of 0FFFFh or less. Therefore, the pointer within a 386 TSS called Bit_Map_Offset(15:0) must contain a value of 0DFFFh or less under all conditions, even when you intend the Bit_Map_Offset to point beyond the limit of the TSS itself.

7. BS16# Must Not Be Asserted During Pipelined Bus Cycles

In datasheet figures 5-16, 5-17, 5-19, and 5-22, the bus size 16 (BS16#) input is shown as "don't care" during T2P and T2l in pipelined bus cycles. This is incorrect. In these figures, BS16# should be high during states T2P and T2l. That is, once address pipelining has been requested by asserting next address (NA#), BS16# must be negated for the remainder of the current bus cycle.

Implications: Don't assert BS16# if NA# has already been sampled asserted in the current bus cycle.

8. Double Page Faults Do Not Raise Double Fault Exception

If a second page fault occurs while the processor is attempting to enter the service routine for the first, then the processor will invoke the page fault (exception 14) handler a second time, rather than the double fault (exception 8) handler. A subsequent fault, though, will lead to shutdown.

Implications: Since double page faults normally do not occur, no workaround is necessary.

9. Alignment of Maximum-Sized Segments

If a maximum-sized code segment (limit=FFFFFFFFh) does not start on a double-word boundary, then a segment limit violation (exception 13) will occur when the processor attempts to fetch the first instruction in the segment. This happens because the prefetcher, which always fetches double words, detects a match with the segment limit, which is one less than the segment base due to wrap around.

Implications: If a maximum-sized segment is used, it should be dword aligned (i.e. the two least significant bits of the segment base should be zero). Dword alignment is sufficient to ensure correct operation of the 80386. In addition, Intel recommends that maximum-sized segments be page aligned (i.e. the lowest 12 bits of the segment base should be zero) for compatibility with future processors.

10. Move from 16-bit Segment/System Register to 32-bit Destination

This clarifies how certain instructions (which imply a 16-bit operand size) behave with various operands and operand sizes. These instructions are: MOV r/m16, Sreg; STR r/m16; SLDT r/m16; and SMSW r/m16. When a 32-bit operand size is selected, and the destination is a register, the 16-bit source operand is copied into the lower 16 bits of the destination register, and the upper 16 bits of the destination register are undefined. With a 16 bit operand size and a register operand, only the lower 16 bits of the destination register are affected (the upper 16 bits remain unchanged). With a memory operand, the source is written to memory as a 16-bit quantity, regardless of operand size. Thus, 32-bit software should always treat the destination as 16-bits, and mask bits 16-31 if necessary.

11. Coprocessor Signals BUSY#, ERROR# and PEREQ Recognized During Hold

In section 5.5.1, the 80386 Data Sheet states that all inputs except HOLD, RESET, and NMI are ignored while HLDA is active. This list is incomplete. In addition to these signals, the 80386 also recognizes BUSY#, ERROR# and PEREQ during the bus hold acknowledge state. This makes sense since these pins are dedicated to coprocessor signaling, which occurs independent of the processor's bus cycle.

Errata

1. Opcode Field Incorrect for FSAVE and FSTENV

Problem: If an FSAVE or an FSTENV is executed in REAL mode or in VIRTUAL 8086 mode, the opcode field stored in memory is incorrect if it should have referred to a coprocessor instruction which transfers either two bytes or ten bytes from memory to the coprocessor. The instruction and operand linear address fields are correctly stored. Note that coprocessor error-handling routines are the only routines possibly affected. Also note that the problem does not occur in PROTECTED mode programs (since no opcode is saved by FSAVE or FSTENV in that case).

Workaround: In REAL mode or in VIRTUAL 8086 mode, the instruction linear address field can be used to read the opcode from memory. Note that the two bytes fetched need to be swapped to yield the image that FSAVE and FSTENV normally stores. The following is a possible fixup sequence.

```
FSTENV [BX]      ;save environment
MOV  CX,[BX+8]    ;get linear IP<19:16>
AND  CX,0F000h    ;treat it like a selector
MOV  SI,[BX+6]    ;get linear IP<15:0>
MOV  FS,CX        ;establish addressability
MOV  CX,FS:[SI]   ;get raw opcode value
XCHG CH,CL        ;swap bytes and
AND  CX,7FFh      ;mask out top bits
;CX now has the opcode -- store back if needed
MOV  SI,[BX+8]    ;get opcode word
AND  SI,0F800h    ;mask out the bad
OR   SI,CX        ;mask in the good
MOV  [BX+8],SI    ;and store back
```

The opcode saved within the FSAVE FSTENV operand is in the following format:

10	9	8		7	6	5	4	3	2	1	0
-----				-----							
lower three bits				mod r/m byte							
of ESC byte											

2. FSAVE, FRESTOR, FSTENV and FLDENV Anomalies with Paging

Problem: If either of the last two bytes of an FSAVE or an FSTENV operand are for any reason not writeable, or either of the last two bytes of an FRESTOR or FLDENV are for any reason not readable, the instruction is not restartable. This problem will arise only in demand-paged systems, or demand-segmented systems which increase segment size on demand.

Workaround: A simple workaround is to write some value into the last two bytes of the FSAVE/FSTENV operand just prior to the instruction, or read the last two bytes prior to an FLDENV/FRESTOR. Another workaround is to avoid having the operand of these instructions cross a page or segment boundary. In paged systems, this can be accomplished by aligning these operands on any 128-byte boundary.

3. Wraparound Coprocessor Operands

Problem: This can affect only situations where a coprocessor operand straddles the limit of a segment of maximum size (i.e. 0FFFFh for a 16-bit segment or 0FFFFFFFFh for a 32-bit segment) or within 108 bytes of maximum size, thus wrapping around to offset 0 of the segment. Since a wraparound situation is very abnormal for a compiler or programmer to create, this does not affect a typical system.

Formally, the 80386 architecture does not permit an operand (coprocessor operands included) to wrap around the end of a segment. If the user

issues such an instruction nonetheless in a Protected Mode system, and the operand starts and ends in valid, present pages of a segment, BUT spans through an invalid or inaccessible page, the coprocessor may be put in an indeterminate state. In such cases, an FCLEX or FINIT instruction needs to be executed before any other coprocessor instruction is issued.

Workaround: In Real Mode, this is not a problem since protection is not enabled. In Protected Mode, this problem is avoided simply by not creating coprocessor operands which wrap around the end of the segment, or by aligning the base of all segments on page boundaries.

4. IRET to TSS with Limit too Small

Problem: If an IRET performs a task switch to a TSS of proper descriptor type but invalid (too small) limit, a Double Fault (exception 8) will result instead of a Invalid TSS Fault (exception 10) as should result. Furthermore, if the Double Fault entry in the IDT is a trap gate, a shutdown results. In a related topic, if the TSS Fault entry in the IDT is invalid for any reason (e.g. bad AR byte), then instead of a Double Fault (exception 8), a shutdown results.

Workaround: A working system, one that creates TSS segments of adequate size to hold the processor state (44 bytes for the TSS of a 16-bit task, 104 bytes for the TSS of a 32-bit task), will not encounter any problems here. A working system should also provide a valid gate (interrupt, trap, or task gate) in the IDT for exception 8.

5. Single-Stepping First Iteration of REP MOVS

Problem: If a REpeated MOVS instruction is executed when single-stepping is enabled (TF = 1 in EFLAGS register), a single-step trap (exception 1) is taken every two move steps, but should occur each move step. Also, if a data breakpoint is hit during an odd iteration number of REP MOVS, the data breakpoint trap is not taken until after the next even-numbered iteration. If the REP MOVS ends with an odd number of iterations, and single-stepping or data breakpoints are enabled, then a single-step trap or data breakpoint trap on the final iteration will properly occur after the final, odd-numbered iteration.

Workaround: When using the Trap Flag or data breakpoints with a debugger utility, this minor variation of REP MOVS must be accepted, unless an effort is made to have the debugger emulate the REP MOVS rather than actually execute it.

6. Task Switch to Virtual 8086 Mode Doesn't Update Prefetch Limit

Problem: When a task switch to Virtual 8086 Mode is performed, the prefetch limit is not updated to become 0FFFFh, but instead remains at its previous value.

Workaround: Use the IRET instruction to transfer to Virtual 8086 Mode. Using IRET is the preferred method for most instances, especially when the master OS dispatches a Virtual 8086 Mode program, because IRET can cause the transition without a task switch.

7. Wrong Register Size for String Instructions in Mixed 16/32-bit Addressing Systems

Problem: If certain string and loop instructions are followed by instructions that either:

- 1) use a different address size (that is, if either the string instruction or the following instruction uses an address size prefix), or
- 2) reference the stack (e.g. PUSH/POP/CALL/RET) and the "B" bit in the SS descriptor is different from the address size used by the string

instructions,

then one or more of (E)CX, (E)SI, or (E)DI is not updated properly. The size of the register (16 vs. 32) is taken from the following instruction rather than from the string or loop instruction. This could result in updating only the lower 16 bits of a 32-bit register, or in updating all 32 bits of a register being used as 16 bits. The instructions and registers affected by this are listed below:

Instruction	Register(s)
MOVS	(E)DI
REP MOVS	(E)SI
STOS	(E)DI
INS	(E)DI
REP INS	(E)CX

Workaround: No workaround is necessary if all code is 16-bit or if all code is 32-bit. The problem only occurs if instructions with different address sizes are mixed together, or if a code segment of one size is used with a stack segment of the other size.

In a system which mixes address sizes, add a NOP after each of the above instructions and ensure that the NOP has the same address size as the string/loop (i.e., if the string/loop instruction includes an address prefix, place the same address prefix before the NOP; conversely, if the string/loop instruction does not have an address prefix, do not place a prefix before the NOP).

8. FAR Jump Located Near Page Boundary in Virtual 8086 Mode Paged Systems

Problem: In Virtual 8086 Mode, if a direct FAR jump (opcode EAh) instruction is located at the end of a page (or within 16 bytes of the end), and the next page is not cached in the TLB, the prefetcher limit is not set by the FAR jump instruction to the "end" on the new code segment, but rather is left at the "end" of the old code segment. This can allow execution beyond the end of the new segment without triggering a segment limit violation. Or it can result in a spurious GP fault if the old and new segments overlap, and a prefetch occurs beyond the limit of the old segment.

Note that the prefetch limit is checked on the linear address, not by comparing IP to 0FFFFh.

Workaround: All existing 8086 programs use only 16-bit addressing, and thus will not execute code at offsets greater than 0FFFFh from the code segment base. Thus the lack of detection of walking off the end of a code segment should not impact working 8086 programs.

A workaround to the spurious GP fault, if it occurs, is to simply IRET back to the faulting instruction, since the IRET will correctly set the prefetch limit. If the fault handler has control of the single-step function, a very simple workaround is to attempt to single-step the faulting instruction. If the single-step succeeded, the handler could clear the fault, turn off single-stepping, and IRET. If a GP fault occurred attempting to single-step the instruction, a "real" GP fault is the cause.

If the fault handler cannot access the single-stepping function, it still can check for "real" GP faults which must be emulated by the master OS, for example, I/O instructions that need to be emulated, CLI/STI instructions that must be emulated, etc. If none of these faults are recognized, the fault handler can assume this errata caused the GP fault and simply IRET back to the instruction.

9. Page Fault Error Code on Stack Not Reliable

Problem: When a Page Fault (exception 14) occurs, the 3 defined bits in the error code may be unreliable if a certain sequence of prefetch is happening at the same time.

Workaround: Although the page fault error code pushed onto the page fault handler's stack can be unreliable, as described, the page fault linear address stored in register CR2 is always correct. The page fault handler should refer to the page fault linear address in CR2 to access the corresponding page table entry and thereby determine whether the page fault was due to a page "not present" condition, or to a usage violation.

10. Certain I/O Addresses Incorrect when Paging is Enabled

Problem: When Paging is enabled, accessing I/O addresses in the range 00001000h-0000FFFFh (4K through 64K-1) or accessing coprocessor ports (I/O addresses 800000F8h-800000FFh) as a result of executing coprocessor opcodes, can generate incorrect I/O addresses if paging is enabled and the corresponding linear memory address is marked "present" and "dirty."

Furthermore, when paging has been enabled and is then turned off, paging translation continues to occur for memory or I/O cycles (I/O as described above) to linear addresses still stored in the TLB, but paging does not occur for linear addresses that result in a TLB miss.

Workaround: Unless paging is used, this item is not a problem. If paging is used but all I/O ports are below 00001000h (as in a PC-DOS system), then I/O is no problem.

If paging is used and I/O ports exist in the range 00001000h-0000FFFFh, then either have the memory pages at those linear addresses marked "not present" (to avoid having those pages table entries cached in the TLB), or if "present," have those pages mapped such that bits 12-15 of the physical address equal bits 12-15 of the linear address. Alternatively, re-assign any I/O ports in the range 00001000h-0000FFFFh to below 00001000h.

If paging is used and the coprocessor is also used, then have the memory page at linear address 80000xxxh either marked "not present" (to avoid having that page table entry cached in the TLB), or if "present," have the page mapped such that bit 31 (the most significant bit) of that page's physical address is a 1.

To completely disable 80386 paging when paging was previously enabled, the 80386 TLB should be flushed immediately after resetting the PG bit in CR0. The TLB can be flushed, you recall, by writing a Page Table Directory base address to register CR3.

11. Wrong ECX Update by REP INS

Problem: The ECX register (or CX in case of 16-bit operations) is not updated properly in the case of a REP INS instruction (INPUT string instruction with any REPEAT prefix) that is followed by an early-start instruction (e.g. PUSH, POP or memory reference instructions). After any REP-prefixed instruction, ECX is supposed to be 0 (null). But in the case of a REP INS instruction, ECX is not updated correctly and is 0FFFFFFFh (or CX is 0FFFFh in case of 16-bit operations). It should be noted that the REP INS executes the correct number of iterations and EDI (or DI) is updated properly.

Workaround: After a REP INS instruction, do not rely on ECX (or CX) being zero. Hence, a new count (if any) should be MOVED into ECX, rather than being ADDED into ECX.

12. NMI Doesn't Always Bring Chip Out of Shutdown in Obscure Condition with Paging Enabled

Problem: If paging is enabled, and if the IDT gate for the Double Fault

handler (the gate for exception 8) points to the null descriptor slot, descriptor 0, in the GDT (this would be very a strange way to set up a system), and a TLB miss occurs when accessing the null descriptor slot, the chip enters shutdown as it should in this case. In this specific case however, an incoming NMI will not be able to bring the 386 out of shutdown. In this specific case, only reset will bring the 386 out of shutdown.

Workaround: Ensure that the IDT gate for the Double Fault Handler has a non-null selectors for CS, and that SS of the destination level is also non-null.

13. HOLD Input During Protected Mode Interlevel IRET when Paging is Enabled

Problem: Under specific situations involving paging and the page privilege bits, the HOLD input, and a RET or IRET instruction performing an inter-level return to level 3, a problem can develop. These situations can be avoided by the workarounds given.

The first situation, when the inner level stack (levels 0, 1, and 2) is not dword aligned (or not word aligned in the case of a 16-bit (I)RET), requires that several conditions occur simultaneously:

- 1) Paging must be enabled, and the page table and directory entries for the inner level stacks must be marked as supervisor access only.
- 2) The software must execute an inter-level RET or IRET to a Protected Mode program at privilege level 3. An inter-level IRET to Virtual 8086 Mode does not exhibit this problem. An inter-level RET or IRET to level 1 or 2 does not exhibit this problem.
- 3) The inner level stack must be unaligned to a dword boundary (word boundary for a 16-bit (I)RET).

When the first situation occurs, a page fault (exception 14) occurs spuriously, indicating a page level protection violation during a "user" level read of the inner level stack.

The second situation, whether or not the inner level stack is dword aligned (or word aligned in the case of a 16-bit (I)RET), also requires that several conditions occur simultaneously:

- 1) Paging must be enabled, and the page table and directory entries for the inner level stacks must be marked as supervisor access only.
- 2) The software must execute an inter-level RET or IRET to a Protected Mode program at privilege level 3. An inter-level IRET to Virtual 8086 Mode does not exhibit this problem. An inter-level RET or IRET to level 1 or 2 does not exhibit this problem.
- 3) The bus HOLD input must be asserted during the read cycle which pops ESP (or SP) off the inner stack as a result of a RET or IRET instruction.

When the second situation occurs, no exception is generated, but the processor will drive an incorrect physical address during the read cycle in which SS is popped from the inner level stack.

Workarounds: A software workaround to both situations is to mark all pages which contain the inner level stacks as user readable. This prevents either the first or second situation from occurring. The segmentation system can be used to prevent user access to the linear addresses containing the inner-level stacks.

A workaround if not using the HOLD input is merely to keep the inner-level stacks aligned.

A Hardware workaround if using the HOLD input but not using the software workaround above is the following: Since the problem occurs during the first cycle after a locked cycle to read the CS descriptor, a hardware workaround is to prevent a HOLD request from hitting the processor during bus cycle following a LOCKed cycle. This can be accomplished with a latch that delays the LOCK# signal through a flip-flop clocked by READY# to gate a HOLD request going into the chip. This will prevent a hold request from getting to the 80386 until after the completion of the first cycle after a LOCKed cycle. For the hardware workaround to be sufficient, all stacks must be properly aligned, and BS16# must be tied inactive.

14. Protected Mode LSL Instruction Should not be Followed by PUSH/POP

Problem: This item pertains only to Protected Mode. If the Protected Mode LSL instruction (Load Segment Limit instruction, executable only in Protected Mode) is immediately followed by certain instructions that perform a stack operation, such as PUSH or POP (see exact list below), the value of the (E)SP register may be incorrect after the stack operation. Note that stack operations resulting from interrupts or exceptions following LSL do update (E)SP correctly.

Workaround: Do not immediately follow the Protected Mode LSL instruction with any of the following stack operation instructions: IRET (intra-task), POPA, POPF, POP (mem, reg, seg-reg), RET (intra-segment or intersegment), CALL (direct intra-segment, direct intersegment, indirect intra-segment via reg), ENTER, PUSHA, PUSHF, PUSH (mem, reg, seg-reg, immed). Other instructions that operate on the stack (e.g. CALL indirect via memory, and LEAVE) can be used safely after the Protected Mode LSL. Note that even if a forbidden instruction immediately follows LSL, (E)SP may still be updated correctly, since this problem is data-dependent and only occurs if the LSL operation succeeded (i.e. if LSL set the ZF flag).

15. LSL/LAR/VERR/VERW Instructions Malfunction with Null Selector

Problem: The Protected Mode instructions LSL, LAR, VERR or VERW executed with a null selector (i.e. bits 15 through 2 of the selector set to zero) as the operand will operate on the descriptor at entry 0 of the GDT instead of unconditionally clearing the ZF flag.

Workaround: The "null descriptor" (i.e. the descriptor at entry 0 of the GDT) should be initialized to all zeros. If the "null descriptor" is initialized to all zeros (i.e. an invalid value), the access made by these instructions to the "null descriptor" will fail (since these instructions only operate on valid descriptors). The failure will be reported with ZF cleared, which is the desired behavior when the operand is a null selector. Note that many systems already have the "null descriptor" in the GDT initialized to zeros, as is desired for this workaround.

16. "Not Present" LDT in VM86 Task Raises Wrong Exception

Problem: A task switch to a VM86 task that has a "not present" LDT descriptor will cause a Segment Not Present fault (exception 11) rather than an Invalid TSS fault (exception 10).

Workaround: The simplest workaround is to use a NULL selector for the LDT in a VM86 task, since the LDT is not used when executing in Virtual 86 mode. However, if an interrupt or exception occurs, the processor will switch out of Virtual 86 mode, into protected mode to handle the interrupt, without switching tasks. Thus, the operating system should be structured so that all Interrupt and Trap gates active when executing a VM86 task reference segments in the GDT.

If an LDT must be supplied for a task that executes in Virtual 86 mode, there are several easy workarounds. One is to ensure that LDT segments are never marked "not present" in their segment descriptors. Paging is

not affected by this errata. LDT segments can be paged out and marked "not present" in their page descriptors in systems which use paging.

If the operating system must mark the LDT segment descriptor "not present", the "not present" (exception 11) handler must be able to handle the case of a "not present" LDT during a task switch. The "not present" exception is reported with the LDT selector as the error code and with the VM bit set to 1 in the EFLAGS image of the caller. Since a VM86 task cannot normally raise a "not present" fault, the "not present" exception handler can detect this case by checking if the stored VM bit is set. If so, the fault can be redirected to the TSS Fault handler.

17. Coprocessor Instructions Crossing Page/Segment Boundaries

Problem: If the first byte of a coprocessor (ESC) instruction is located on the last byte of a page or segment, and the second byte is located on a page or segment which would create a fault, then the processor will hang when it tries to signal the fault. The processor remains stopped until an interrupt, NMI, or RESET occurs. This errata applies only to coprocessor instructions in systems which use virtual memory.

Workaround: In virtual memory systems, the time-slice or watchdog timer provides an easy workaround, since a timer interrupt will always cause the processor to begin interrupt processing. The timer routine should test the following conditions to determine if this errata was encountered.

- 1) The saved CS:EIP must point within 8 bytes of the end of a page.
- 2) The last byte within the page must contain an ESC opcode.
- 3) All bytes between the saved CS:EIP and the ESC opcode must contain valid prefix opcodes (segment override 26h, 2Eh, 36h, 3Eh, 64h, 65h, address size override 67h, operand size override 66h).
- 4) The next page is not present, or not accessible.

If all four conditions are true, then the timer routine can assume this errata was encountered, and signal a page fault, which will clear the condition. This workaround should be placed in the Operating System, so that applications programs are unaffected.

18. Breakpoints Malfunction after Reading CR3, TR6, or TR7

Problem: Breakpoints associated with the four debug registers (DR0-3) will not work correctly after a MOV from CR3, TR6 or TR7 is executed. The contents of DR0-3 are unaffected; however, spurious breakpoints may result. This condition persists until the processor executes the next jump instruction. This errata does not affect the breakpoint instruction (opcode 0CCh) or the single-step trap (TF, bit 8 in EFLAGS).

Workaround: Breakpoints will work correctly if the following sequence is always used to read CR3, TR6, or TR7.

- 1) Disable breakpoints by clearing G0-G3, L0-L3 in DR7
- 2) MOV from CR3, TR6, or TR7 to the destination
- 3) Jump to the next instruction
- 4) Re-enable breakpoints

19. Return Address Incorrect for Segment Limit Fault during FNINIT

Problem: In protected mode, if the segment limit is set so that the last byte of an FNINIT opcode falls on the last byte of a segment, then the processor will indicate a segment limit fault (exception 13), with the return address (saved on the stack) pointing to the FNINIT opcode. Since the FNINIT opcode falls entirely within the segment, the return address should point to the next instruction.

Workaround: In systems which restart instructions on segment limit faults, the exception handler should test for an FNINIT instruction at the end of a segment and adjust the return address accordingly. Alternatively, the exception handler can leave the return address unchanged, and allow the FNINIT to be executed a second time. In systems in which walking off the end of a segment indicates a nonrecoverable software error, no workaround is necessary.

20. VERR/VERW/LAR/LSL Instructions Malfunction with Bad Selector

Problem: If the operand of a VERR, VERW, LAR, or LSL instruction is not accessible (due to the selector value exceeding the GDT/LDT limit or a null LDT), and no instruction following the VERR/VERW/LAR/LSL (in the prefetch queue) is a JMP or CALL or has a memory operand, then the processor will hang up after executing the VERR/VERW/LAR/LSL. The processor remains stopped until an interrupt, NMI, or RESET occurs. This errata applies only to the protected mode.

Workaround: No workaround is necessary in systems with a timer interrupt. If the processor stops as a result of this errata, the timer interrupt will cause the processor to begin interrupt processing. Upon completion of the interrupt handler (via IRET), the processor will resume execution with the instruction following VERR/VERW/LAR/LSL.

If a timer interrupt is not available, another workaround is to follow each VERR/VERW/LAR/LSL instruction with a JMP or Jcc instruction. To work correctly, both instructions must be aligned so that the last byte of the VERR/VERW/LAR/LSL instruction, and all bytes of the JMP instruction, reside in the same doubleword. This guarantees that the processor will have fetched the entire JMP instruction before executing the VERR/VERW/LAR/LSL.

21. Coprocessor Malfunctions with Paging Enabled

Problem: Under certain conditions of memory wait-states and HOLD requests, a problem can occur. If paging is enabled, and the prefetch unit (internal to the 80386) requests a memory read cycle at the same time that the coprocessor requests an operand transfer cycle (by asserting PEREQ), then the processor may drive out an incorrect address when transferring data from the coprocessor. Specifically, the processor will drive an I/O address of 000000FCH (with A31 low), rather than 800000FCH (with A31 high). As a result, the 80387 may be left in an indeterminate state. This errata occurs only when the 80386 is executing an ESC instruction with a memory operand while paging is enabled.

Workaround: Several workarounds are possible. The recommended hardware-only workaround is to add a state machine which prevents the PEREQ signal from hitting the processor while the prefetcher may be active. The state machine should monitor the processor's bus activity. If the bus is idle for more than eight clocks (while HLDA is negated), the state machine can assume the prefetch queue is full and allow the 80387 PEREQ to be passed on to the 80386. Otherwise, 80386 PEREQ should be forced inactive. A PAL implementation of this workaround is provided in a separate document. Note that this method of determining when the prefetch queue is full works only during ESC instructions with memory operands, since the processor must wait for the ESC to finish before executing any subsequent instructions.

Another hardware-only workaround is possible if no I/O device exists at address 000000FCH. If the processor performs an I/O cycle to this address, an external decoder can assume the I/O cycle is intended for the coprocessor, and enable the coprocessor accordingly. Note that decoding the I/O address will require 15 ns if implemented in a B-PAL. Thus, a state machine must be provided which asserts the 80387 ADS# pin one clock after 80386 ADS#, to allow sufficient time to decode.

An OS/hardware workaround is to locate the Page Directory Table at address 80001000H or higher (i.e. CR3 bit 31 is set). If memory is not available at address 80001000H, the hardware should be modified to ignore A31 when decoding memory addresses (A31 should still be used as a coprocessor select). This may be accomplished by disconnecting the system's A31 from the processor, and connecting it to A30.

An OS-only workaround is to set the EM bit in CR0, forcing the processor to trap on every ESC instruction. The OS can then execute the ESC instruction in a controlled environment. Specifically, within the exception 7 handler, the ESC instruction should be followed by a JMP. Both instructions should be aligned so the last byte of the ESC instruction, and all bytes of the JMP reside within the same doubleword. Aligning the instructions in this manner guarantees that the processor will have prefetched the entire JMP instruction before executing the ESC. By stopping the prefetcher, the JMP prevents this errata from occurring. Before implementing this workaround, the OS must first check the 80386 revision identifier (in DX after RESET) to determine if a workaround is necessary. Note that using this workaround will have significant performance impact on numerics software. Care should be taken to ensure that any OS workaround also satisfies errata 10.

Design Notes

1. Read Cycles Require Valid Data Bus Levels

Please refer to Specification Change 5 for important news on proper system design for 386 read cycles.

2. Use of ESP as a Base Register With CALL, PUSH, and POP Instructions

This clarifies how ESP behaves with instructions that implicitly reference the stack and explicitly reference another location in memory using ESP as a base register.

Instruction	Explicit Memory Reference uses the ESP value...	ESP value used as base
CALL-indirect-thru-memory	before decrementing	old ESP
PUSH-from-memory	before decrementing	old ESP
POP-to-memory	after incrementing	new ESP

This is consistent in that the CALL-indirect-thru-memory and the PUSH-from-memory both use the same ESP value.

Furthermore, the relation between PUSH-from-memory and POP-to-memory is such that it allows the instruction sequence:

PUSH [ESP+n]

POP [ESP+n]

to have the desirable property of both instructions referencing the same memory location.

3. Use of Code Breaks to Debug 86/286 Operating Systems

The RF bit in the EFLAGS register is cleared by a 16-bit IRET, making it difficult to use the on-chip debug registers to set code breakpoints to debug 16-bit operating systems. Data breakpoints work fine in all cases, and code breakpoints work fine as long as all interrupt handlers are 32-bits and return with 32-bit IRETs or task switches. In 16-bit environments, software debuggers should use the CC (single byte INT 3 instruction) to place software breakpoints in code.

4. Use of ESP in 16-bit Code with 32-bit Interrupt Handlers


When a 32-bit IRET is used to return to another privilege level, and the old level uses a 4G stack (B=1), while the new level uses a 64k stack (B=0), then only the lower word of ESP is updated. The upper word remains unchanged. This is fine for pure 16-bit code, as well as pure 32-bit code. However, when 32-bit interrupt handlers are present, 16-bit code should avoid any dependence on the upper word of ESP. No changes are necessary in existing 16-bit code, since the only way to access ESP in USE16 segments is through the 32-bit address size prefix.

A Hardware Workaround for the 80386 Paging/Coprocessor Errata

This document describes a simple hardware workaround for the 80386 Paging/Coprocessor errata. The workaround is software transparent, creates no timing problems, and is suitable for daughtercard construction. It does *not* affect processor performance on non-numeric programs, but will have a slight performance impact on numeric programs. The circuit we're about to describe has been built and tested in several 80386 machines. As always, complete PAL codes and schematics are included. For a description of the errata, consult the *80386 Stepping Information*, dated 9-1-87, errata number 21.

The workaround consists of adding a PAL to control the PEREQ (Processor Extension REQuest) signal received by the 80386. The basic idea is to prevent a PEREQ from hitting the processor at a time when a prefetch request may be pending internally. Specifically, the PAL contains a state machine to monitor 80386 bus activity, a counter to keep track of idle cycles, and a state machine to mask PEREQ if necessary.

The operation of the circuit is as follows. During active bus cycles, the counter is cleared. When an idle cycle occurs (with HLDA negated) the counter is incremented. When 8 idle cycles have been counted, the circuit assumes the prefetch queue is full and allows a PEREQ to pass through to the 80386. Otherwise, 80386 PEREQ is forced inactive. Thus, a coprocessor request can only be honored *after* the prefetcher has stopped. By monitoring the processor's bus cycles, the circuit functions properly for all combinations of HOLD requests and memory wait-states. In applying this circuit, one should allow at least 8 clocks between consecutive HOLD requests, in order to let ESC instructions complete. Also note that this method of determining when the prefetch queue is full works only during ESC instructions with memory operands, since the processor must wait for the ESC to finish before executing any subsequent instructions.



PEREQ CONTROL
ED GROCHOWSKI 8-27-87

```

module pereqmod;
flag '-r3';
title 'PEREQ mask ed grochowski 8/24/87 intel corporation'

```

```

"This PAL accepts status information from the 80386 and uses it
to track bus cycles. This PAL generates a gated PEREQ output, which
is activated only when the prefetch queue is full.

```

```

pall device 'p16r8';
h,l,c,x = 1,0,.C.,.X.;

```

```

gnd pin 10;
vcc pin 20;
oe pin 11;

```

```

clk2 pin 1;      "80386 CLK2
reseth pin 2;    "high during reset
ads pin 3;       "low to begin bus cycles
ready pin 4;     "low to end bus cycles
mio pin 5;       "high during memory cycles, low for i/o
dc pin 6;        "high for data, low for code
hlda pin 7;      "high during hold acknowledge
busy pin 8;      "low when coprocessor is busy
perreq pin 9;    "high during coprocessor operand transfers

```

```

pereqgate pin 12; "gated PEREQ to the processor
resetd pin 13;    "reseth delayed by one CLK2 period
clk pin 14;       "low during phase 1, high during phase 2
pipecyc pin 15;   "low after pipelined bus cycles
buscyc pin 16;    "low during active bus cycles
icnt0 pin 17;     "idle counter bit 0
icnt1 pin 18;     "idle counter bit 1
icnt2 pin 19;     "idle counter bit 2

```

```

idle      = [1,1];
active     = [0,1];
pipelined = [1,0];
illegal   = [0,0];

```

```

inuse = [1,1,1];
idle2 = [0,1,1];
idle3 = [1,0,1];
idle4 = [1,1,0];
idle5 = [0,0,1];
idle6 = [1,0,0];
idle7 = [0,1,0];
idle8 = [0,0,0];

```

```

"clk generator

```

```

equations resetd := reseth;
equations clk := !(clk & (!reseth & resetd));

```

```

"bus cycle tracking

```

```

state_diagram [buscyc,pipecyc]
state idle:
    if (reseth) then idle
    else if (!ads & clk) then active
    else idle;

```

```

state active:
    if (reseth) then idle
    else if (!ready & ads & clk) then idle

```

```

else if (!ready & !ads & clk) then pipelined
else active;

```

```

state pipelined:
  if (reseth) then idle
  else if (clk) then active
  else pipelined;

```

```

state illegal:
  goto idle;

```

"idle cycle counter

```

state_diagram [icnt0,icnt1,icnt2]
state_inuse:      "bus in use, or idle 1 clock
  if ([[buscyc,pipeccyc]==idle) & ads & !hlda & clk) then idle2
  else inuse;

```

```

state idle2:      "2 clocks idle
  if ([[buscyc,pipeccyc]==idle) & ads & !hlda & clk) then idle3
  else if (clk) then inuse
  else idle2;

```

```

state idle3:      "3 clocks idle
  if ([[buscyc,pipeccyc]==idle) & ads & !hlda & clk) then idle4
  else if (clk) then inuse
  else idle3;

```

```

state idle4:      "4 clocks idle
  if ([[buscyc,pipeccyc]==idle) & ads & !hlda & clk) then idle5
  else if (clk) then inuse
  else idle4;

```

```

state idle5:      "5 clocks idle
  if ([[buscyc,pipeccyc]==idle) & ads & !hlda & clk) then idle6
  else if (clk) then inuse
  else idle5;

```

```

state idle6:      "6 clocks idle
  if ([[buscyc,pipeccyc]==idle) & ads & !hlda & clk) then idle7
  else if (clk) then inuse
  else idle6;

```

```

state idle7:      "7 clocks idle
  if ([[buscyc,pipeccyc]==idle) & ads & !hlda & clk) then idle8
  else if (clk) then inuse
  else idle7;

```

```

state idle8:      "8 clocks idle
  if ([[buscyc,pipeccyc]==idle) & ads & !hlda & clk) then idle8
  else if (clk) then inuse
  else idle8;

```

"coprocessor operand request

```

state_diagram [pereqgate]
state 0:          "no coprocessor request
  if (pereq & ([icnt0,icnt1,icnt2]==idle8) & ads & !hlda & clk) then 1
  else 0;

```

```

state 1:          "coprocessor request
  if (!pereq & clk) then 0
  else 1;

```

```
test_vectors ([clk2, reseth, ads, ready, hlda, busy, pereq, oe] ->
              [clk, pereqgate, pipecyc, buscyc])
```

```

[c,h,h,h,1,h,1,1] -> [x,x,x,x];
[c,h,h,h,1,h,1,1] -> [x,x,x,x];
[c,1,h,h,1,h,1,1] -> [1,1,h,h];    "synchronize phase
[c,1,h,h,1,h,1,1] -> [h,1,h,h];
[c,1,h,h,1,h,1,1] -> [1,1,h,h];
[c,1,h,h,1,h,1,1] -> [h,1,h,h];
[c,1,h,h,1,h,1,1] -> [1,1,h,h];

[c,1,1,h,1,h,1,1] -> [h,1,h,h];    "ads asserted
[c,1,1,h,1,h,1,1] -> [1,1,h,1];
[c,1,h,h,1,h,1,1] -> [h,1,h,1];    "one wait-state
[c,1,h,h,1,h,1,1] -> [1,1,h,1];
[c,1,h,1,1,h,h,1] -> [h,1,h,1];    "ready, pereq asserted
[c,1,h,1,1,h,h,1] -> [1,1,h,h];

[c,1,h,h,1,h,h,1] -> [h,1,h,h];    "1 clock idle
[c,1,h,h,1,h,h,1] -> [1,1,h,h];
[c,1,h,h,1,h,h,1] -> [h,1,h,h];    "2 clocks idle
[c,1,h,h,1,h,h,1] -> [1,1,h,h];
[c,1,h,h,1,h,h,1] -> [h,1,h,h];    "3 clocks idle
[c,1,h,h,1,h,h,1] -> [1,1,h,h];
[c,1,h,h,1,h,h,1] -> [h,1,h,h];    "4 clocks idle
[c,1,h,h,1,h,h,1] -> [1,1,h,h];
[c,1,h,h,1,h,h,1] -> [h,1,h,h];    "5 clocks idle
[c,1,h,h,1,h,h,1] -> [1,1,h,h];
[c,1,h,h,1,h,h,1] -> [h,1,h,h];    "6 clocks idle
[c,1,h,h,1,h,h,1] -> [1,1,h,h];
[c,1,h,h,1,h,h,1] -> [h,1,h,h];    "7 clocks idle
[c,1,h,h,1,h,h,1] -> [1,1,h,h];
[c,1,h,h,1,h,h,1] -> [h,1,h,h];    "8 clocks idle
[c,1,h,h,1,h,h,1] -> [1,h,h,h];
[c,1,h,h,1,h,h,1] -> [h,h,h,h];    "9 clocks idle, pereqgate asserted
[c,1,h,h,1,h,h,1] -> [1,h,h,h];
end pereqmod;
```

Device pall

Reduced Equations:

```
resetd := !(reseth);

clk := !(clk # resetd & !reseth);

buscyc := !(buscyc & clk & !pipecyc & !reseth
# !ads & buscyc & clk & !reseth
# !buscyc & !clk & pipecyc & !reseth
# !buscyc & pipecyc & ready & !reseth);

pipecyc := !(buscyc & !clk & !pipecyc & !reseth
# !ads & !buscyc & clk & pipecyc & !ready & !reseth);

icnt0 := !(clk & !icnt0
# ads & buscyc & clk & !hlda & !icnt2 & pipecyc
# ads & buscyc & clk & !hlda & icnt0 & icnt1 & pipecyc);

icnt1 := !(clk & !icnt1
# ads & buscyc & clk & !hlda & !icnt0 & pipecyc
# ads & buscyc & clk & !hlda & icnt1 & !icnt2 & pipecyc);

icnt2 := !(clk & !icnt2
# ads & buscyc & !hlda & !icnt0 & !icnt2 & pipecyc
# ads & buscyc & clk & !hlda & !icnt1 & pipecyc);

pereqgate := !(ads & !pereqgate
# !clk & !pereqgate
# hlda & !pereqgate
# icnt0 & !pereqgate
# icnt1 & !pereqgate
# icnt2 & !pereqgate
# clk & !pereq);
```